Approved For Release 2001/04/23 : CIA-RDP78-02820A000800050022-4

The Files

28 August 1962

25X1A9a

Trip Report

1. On August 8, 1962 author flew to the investigate reported problems with the number two prototype K2-22.

25X1A6b

- 2. After cleaning the printed circuit contacts, it was noted that the unit did not work with a certain sequence of numerals. The circuit was modified and the unit worked satisfactorily.
- 3. Some of the personnel were briefed on the theory of operation of the KE-22 and a spare set of printed circuit boards were left in case any further trouble developed.

25X1A6b

- 4. Author returned to the Laboratory on August 16, 1962 and made a modification on all of the production grinted circuit boards to prevent this problem from recurring.
- 5. Some changes, us suggested by are being incorporated in the final schematic diagram.

25X1A9a

- 6. The trip was very worthwhile as it enabled the Lab to correct certain faults with the equipment before all units were delivered to the field.
- 7. Author would like to thank and the rest of the personnel at for being so accommodating and making the trip a very pleasant one.

25X1A9a 25X1A6b

25X1A9a

Lab/RBO/rkb (28 August 1962)

Distribution:

Original - Addressee

L - OC-AD

£ -

25X1A6b

1 - RELD

1 - Dev/s

i - Lab Project Folder

2 - Monthly Report &

